



Exhibit A – Pictures of Existing Conditions



Picture 01 – Close up of Window Crack.




Picture 02 – Front overall view of Interior Side.

Exhibit A – Pictures of Existing Conditions



Picture 03 – Exterior overall view.



Picture 4 - Overall Isometric View_1



Picture 5 - Overall Isometric View_2